

DESCRIPTION

Patented PVC tight fibered cotton composite corner tape that is 2" wide, .013" thick and comes in 50', and 100' rolls. Crack-Tape repairs difficult cracks on flat surfaces and corners. Tested to be two times stronger than tapes, the tape repairs stress cracks and cracks due to truss uplifts

ADVANTAGES

- Drywall and plaster cracks, and truss uplift repairs.
- Persistent cracks.
- Thin coat plaster applications.
- Repairs cracks and holes in plaster surfaces quickly and easily using all purpose joint compounds.

WARRANTY

Strait-Flex products are backed by a lifetime warranty. When applied to a sound structure, built on a permanent foundation using recommended application techniques, we warrant that these products will not edge-crack for the lifetime of the structure. Not recommended where structural movement may occur. Contact Strait-Flex International Inc for complete details.

DIRECTIONS

- Measure damaged area and cut Crack-Tape using a scissors or utility knife. For corner applications, fold in half at center crease and adjust to desired angle.
- With a 5" or 6" taping knife, apply a smooth, liberal coat of all-purpose compound to corner or surface crack.
- Press Crack-Tape into the wet compound. Adjust if necessary to create a straight line. Wipe down tight to surface with taping knife using even pressure.
- Immediately apply a light skim coat of compound over surface of Crack-Tape. Wipe down smooth. Let dry completely over several hours or overnight.
- With a 6" or 8" taping knife, apply a second coat of compound directly over Crack-Tape feathering the compound beyond previous coat. For drywall, lightweight compound used in this step makes sanding much easier. Let dry completely over several hours or overnight.
- If further feathering is required, apply another coat of compound using a 6" or 8" taping knife. Extend the compound on both sides by starting from the middle of Crack-Tape. Let dry completely over several hours or overnight.
- Sand lightly with 120 grit sandpaper. Crack-Tape will not fuzz-up like paper or mesh tapes.

STORAGE

Store in dry place protected from moisture.

SUBMITTAL APPROVALS

JOB NAME

CONTRACTOR

DATE

